

SUBJECT: POTENTIAL RELAY WIRING IMPROVEMENT

Number: 15-13
Product: Cubers
Date Issued: December 15, 2015
From: Technical Service

Ice-O-Matic has made a change to the wiring of the Compressor Potential Relay. This change will relocate the Compressor wire from the Potential relay at PR5 to the Contactor at CTT1. This change will begin with the following model numbers:

ICE0500A6
ICE0500T7

ICE0605A6
ICE0605W6
ICE0606A6
ICE0606W6
ICE0606WN6
ICE0606ABR1
ICE0606T7
ICE0606TBR1
ICE0606TN7
ICE0605R7
ICE0606R7

ICE0726R2
ICE0926R2

ICE0520A7
ICE0520AN7
ICE0520T2

ICE0805A5
ICE0806A7
ICE0806W6
ICE0855GA3
ICE0856GA3


ICE1006A8
ICE1006FABR3
ICE1006AN8
ICE1006W7
ICE1006WN7
ICE1006R8
ICE1007A7

Note: The ICE0806A6 was not manufactured.

ICE1506HT1
ICE1506R6

ICE1405A6
ICE1405W6
ICE1405R6
ICE1406R4
ICE1406A7
ICE1406W6
ICE1407R6
ICE1806R6
ICE1806W6
ICE1806WN6
ICE2106R6
ICE2106W6
ICE2106WN6

The Compressor wire, either Red or Black was relocated from Terminal 5 on the Potential Relay to the Contactor CTT1 Terminal



The Service manuals will be updated as required.

If you have any questions, please contact the Ice-O-Matic Service Department at 1-800-423-3367