

**SUBJECT: ICE1006 REMOTE COMPRESSOR**

**Number: 12-14**  
**Product: Cuber**  
**Date Issued: June 2012**  
**From: Technical Service**

Due to manufacturing considerations, the compressor for the ICE1006 Remote cooled condenser has been changed.

For ICE1006 Remote Cooled Version 1, 2, 2A, 3 & 4 the original compressor is no longer available. The replacement kit includes: a new compressor, starting components, liquid line drier and a suction line tubing adapter. This kit enables all versions to use the new compressor.

<u>Model Number</u>	<u>Part Number</u>	<u>Description</u>
ICE1006 Remote <u>Versions 1, 2, 2A, 3 &amp; 4</u>	9181090-11	Replacement Kit <b>NLA</b>

Replacement Compressor Kit for above model.

<u>Model Number</u>	<u>Part Number</u>	<u>Description</u>
ICE1006 Remote <u>Versions 1, 2, 2A, 3 &amp; 4</u>	9181141-11	Replacement Kit

Replacement Compressor Kits for model listed below.

<u>Model Number</u>	<u>Part Number</u>	<u>Description</u>
ICE1006 Remote <u>Version 5</u>	9181141-11	Replacement Kit

**Caution:** As with all compressor replacements, the system will require a cycle check and adjustment of product controls to allow the maximum capacity output for the customer.