

**SUBJECT: LOWER CURTAIN ASSEMBLY – ALL CIM
Part # 9051823-01**

**Number: 2020-01
Product: CIM Cubers
Date Issued: JAN 2020
From: Technical Services**

Continuing our efforts for Product improvement, we have updated the Lower Curtain Assembly to aid in water redirection on the bottom of the Evaporator. On any CIM Cuber with broken tabs on the Water Return at the bottom of the Evaporator, installing the new Curtain will assist in water being directed back into the Water Sump.



Extended tab on Curtain directs water into the Sump.



Trim remaining tabs from Evaporator(s)

